

Quick Start Guide

X-7 USB Recording Device

Telephone Coiled Cord



USB Cable


DO NOT Connect the X-7 USB recording device to your PC until the software is loaded.

Load Software on your PC

Step 1: Download the Desktop Interface Software

Access the Internet from your PC and go to : <http://www.xbluenetworks.com/x7software/X7setup.exe> to download the desktop interface for the X-7 USB recorder software.

The USB recorder supports Windows™ XP SP2, Vista and Windows7™ operating systems.



If ".net Framework", which comes with your Windows™ operating system, is not active on your PC, setup will automatically prompt you through the activation process. The ".net Framework" is required to run the USB recorder.

You must restart your computer after setup is complete

Connecting the X-7 to Your Telephone

Step 2:

Remove the telephone handset cord from the telephone.



Step 3:

Connect the handset cord to the right side of the X-7, labeled "Handset"



Step 4:

Connect the provided telephone coiled cord to the back of the X-7, labeled "Base"



Step 5:

Connect the other end to the telephone where the handset cord was removed.



Connecting the X-7 to your PC

Step 6:

Connect the square end of the USB cable to the back of the X-7 USB recorder



Step 7:

Connect the other end of the cable to a USB port on your PC.

